



Montageanweisung Assembly Instruction

Alle Rechte vorbehalten / all rights reserved © Telegärtner K.Gärtner GmbH D-71144 Steinbronn Lerchenstrasse 35 Germany Phone: +49 7157/125-0 Fax: +49 7157/125-120 www.telegartner.com

Kabelgruppe / cable group G 10 (UT-141)




Kabelgruppe / cable group G 11 (UT-85)




Kontaktstift / contact pin

weichlöten
solder



Gehäuse / housing

weichlöten
solder



Änd./ rev. index	Änderung/ revision code	Datum/ date	Name/ name
Original	A4	Blatt / sheet von / of 1	

	Datum / date	Name / name
gez. / drawn	11.01.07	GE
gepr. / appr.	12.01.07	GB
Maßstab / scale	2:1	

Benennung / title		Serie QLS Lötversion Series QLS solder version
Untert. / doc. type	R T00100C0029	
Ersatz für / replaces		

